

Date:
09/05/2013

Ref:
KPCT/2013/CIR/14

From:
Abu Dhabi Terminals

To:
All Shipping Lines,
Agents, Traders,
Transporters and
Port Users

Subject: Improved empty container inspection opportunities at Khalifa Port.

Dear Valued Customers,

We are pleased to advise that as from 15th May 2013, container owners and operators that wish to have their empty containers go through a standard physical inspection before gating-in at the Khalifa Port Container Terminal have a choice of two fully licensed companies.

The two companies - MECRC (Middle East Container Repair Company LLC) and DBCS (Donovan Bernard Container Services LLC) will in addition to their existing suite of maintenance and repair services, also offer physical inspections of empty containers at their premises in Khalifa Port.

The inspections are carried out on a “drive-thru basis” for drivers bringing one container per trailer or chassis, meaning that:

- The service is fast, prevents the need for grounding the container, and can be done en route to the container terminal;
- Both companies are online with the container terminal, and will thus directly update Abu Dhabi Terminals’ system with a “sound” or “damaged” status;

You will, of course, also have the added benefit of being able to deal immediately with any damages found, before the container is gated-in at the Khalifa Port Container Terminal for either pick-up by exporters or repositioning. Please advise either organization your preferred contacts and instructions directly for this process.

With these new services in place, the temporary inspections at the Khalifa Port Container Terminal gate will no longer be available as from 1st June 2013.

For further information about the services offered:

Company	DBCS	MECRC
Hours	Saturday-Friday: 24 hours	Saturday-Thursday: 24 hours Friday: Closed
Contact	<u>Operations:</u> Jaison Joseph operations@dbcs.me +971 (55) 7763009 <u>Yard:</u> +971 (50) 4948639 <u>Sr. Management:</u> +971 (55) 9900018	<u>Branch Manager:</u> C.J. Christopher +971 (56) 7481590 abm@mecrc.ae <u>Coordinator:</u> Safdar Mujawar coordinator2auh@mecrc.ae <u>Inspections:</u> inspection1auh@mecrc.ae
Standard inspection fee	No charge	AED 5.00 per container
Location Map	Attached Separately	Attached Separately